

Building fabric to be retained

Building fabric to be removed

Proposed interventions

Any surviving windows to be retained and repaired. This includes the semi lunar windows at the rear elevation. New windows to replace missing and damaged windows to be modeled on

the surviving windows.

Refer to Conservation Report prepared by JCA Architects for further details on Protected Structures

Revision Description	Date	Rev. NO.	issued by
SDH Application	08-09-2019	3	AW
SHD Pre application	22-03-2019	2	SV
Planning	15-02-2019	1	IT
igured dimensions only to be used. This drawing is copyright of O'Mahony	Pike Architects Ltd. All info	rmation is sha	red as per
approved use in accordance with BS1192(2007) + A2(2016), Table 5; Standa	d Codes for Suitability of N		
f 'Information Approval Check' is empty, this information has been shared a	t SO - WIP.		

	hom	umika		Project No.:	1623	Scale @ A3:	1:100
nahony pike			Project Lead:	СК	Date Printed:	08-09-2019	
	oan design	Dublin	Cork 26 South Mall	Drawn By:	п	Current Rev.:	3
@omano L 202 7400 1 283 082		The Chapel Mount St. Anne's Milltown, Dublin 6	Cork City	Model No.:	HQDRQ-OMP-P	S1-XX-DR-A-0	900
honypike.com D06 XN52 Ireland T12 R2RV Ireland		Purpose:	S4				
:	Horgan'	gan's Quay s Quay, Cork elopments Lt					
Title: No.:		naster's Build -OMP-PS1-G	0		-As Proposed	Suitability - Cl	necked By - Dat